

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-014996**Date Inspected:** 21-May-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	N/A	CWI Present:	Yes	No			
Inspected CWI report:	Yes	No	N/A	Rod Oven in Use:	Yes	No	N/A
Electrode to specification:	Yes	No	N/A	Weld Procedures Followed:	Yes	No	N/A
Qualified Welders:	Yes	No	N/A	Verified Joint Fit-up:	Yes	No	N/A
Approved Drawings:	Yes	No	N/A	Approved WPS:	Yes	No	N/A
				Delayed / Cancelled:	Yes	No	N/A
Bridge No:	34-0006	Component:	OBG COMPONENT				

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, Subhasis Bera was present during the times noted above for observations relative to the work being performed.

Ultrasonic Testing (UT)

This QA Inspector performed Ultrasonic testing (UT) 10% of the area previously tested and accepted by ZPMC Quality control personnel. This QA inspector generated a (UT) report for this date. The members are identified as segment 10AW.

The weld designations reviewed are as follows:

SP497B-15, 16
SEG059D-019,092
SEG059E-13,18,21,27,30,31
SSD11A-PP87-186,186
FB027-009-165
FB019-005-165

Magnetic Particle Testing (MPT)

This Quality Assurance (QA) Inspector performed Visual inspection and verification of Magnetic Particle Testing (MT) 15% for Segment 10AW. This QA inspector generated a (MT) report for this date. This weld was previously

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

tested and accepted by ZPMC QC MT technicians.

SSD12A-PP88-170/171,175/176,183

Ultrasonic Testing (A, B, C and D-Scan)

This QA Inspector performed Ultrasonic testing (UT) 10% of the area previously tested and accepted by ZPMC Quality control personnel. This QA inspector generated a (UT) report for this date. The members are identified as portion corner joint between Side plate to Edge Plate of segment 10AW. The result was recorded onto a data sheet according to rejection criteria of "D" Scan procedure that Caltrans QA filled out on this date. No rejectable indication found at scanning area.

The Weld Designation is as follows

SEG059A-032,035

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

No relevant conversations

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Bera, Subhasis	Quality Assurance Inspector
----------------------	----------------	-----------------------------

Reviewed By:	Patterson, Rodney	QA Reviewer
---------------------	-------------------	-------------
